

COOPER'S CAMP MUNICIPALITY
CONSTRUCTION SITE FIRST VISIT REPORT

First Visit : PROP-01785 - Ramkrishna GSFP School

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Ramkrishna GSFP School	22.5797224 88.4136035	6	30	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Institutional Toilet Block	1	1	2	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	NA	158	NA	NA	Magurkhali	

Foundation upto Tie beam with reinforcement details

Visit Date

24/02/2026

Earth Cutting
(1200 x 1200 x 1000)

Column Nos.	Length (M)	Breath (M)	Height (M)	Status	Remarks
10	1200	1200	1000	MISMATCH	1st level construction completed before IFA visit

Earth Cutting Image



Re-inforcement

Footing
(10 mm dia 10 nos both)

Rod Nos.	Diameter (M)	Status	Remarks
10	10	MISMATCH	1st level construction completed before IFA visit

Footing Image



Column
(12 mm dia 6 nos)

Rod Nos.	Diameter (M)	Length (M)	Height (M)	Status	Remarks
6	12	250	250	MISMATCH	1st level construction completed before IFA visit

Column Image



Tie beam
(12 mm dia 4 nos)

Rod Nos.	Diameter (M)	Length (M)	Breath (M)	Status	Remarks
4	12	250	250	MISMATCH	1st level construction completed before IFA visit

Tie beam Image



Overall Work Status - Images

Photo 1 - Angle 1



Photo 2 - Angle 2



QR Code Board Image



Signatures & Approval

Seal with signature of ULB Engineer
Name : _____
Contact no. : _____

Signature of Engineer
HILLI INSPIRATION
Name : _____
Contact no. : _____