



SAINTHIA MUNICIPALITY CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-01612 - HARIJAN PRIYAMARY SCHOOL

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
HARIJAN PRIYAMARY SCHOOL	22.5797351 88.4135352	10	22	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Institutional Toilet Block	1	2	2	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	3296	95	NA	NA	SAINTHIA	

Construction Site Second Visit Report

At the time of Roof Casting - Visit Details

Visit Date	18/05/2026			
Roof Beam Top Support (16 mm dia, 4 nos.)	Rod Nos.	Diameter (mm)	Status	Remarks
	4	16	OK	OK

Roof Beam Top Support Image



Roof Beam Bottom Support (16 mm dia, 2 nos.)	Rod Nos.	Diameter (mm)	Status	Remarks
	2	16	OK	OK

m Support Image



Roof Beam Mid Span Top Support
(16 mm dia 2 nos)

Rod Nos.
2

Diameter (mm)
16

Status
OK

Remarks
OK

Roof Beam Mid Span Top Support Image



Roof Beam Mid Span Bottom Support
(16 mm dia 4 nos)


Rod Nos.
4

Diameter (mm)
16

Status
OK

Remarks
OK

Roof Beam Mid Span Bottom Support Image



Roof Details Parameters
(8 mm dia 125 nos)


Diameter (mm)
8

Depth (mm)
125

Status
OK

Remarks
OK

Roof Details Parameters Image



Status	Remarks
OK	OK
OK	OK
OK	OK
OK	OK

Roof beam Mid Span Support

Order for Roof beam dia 125mm C/C

Overall Remarks

OK

Overall Work Status - Images

Photo 1 - Angle 1



Photo 2 - Angle 2



Signatures & Approval

Debarpu *Debarpu*
 CITE

Seal with signature of U.I.B Engineer

Name: _____
Contact no: _____

Debarpu
 Co-ordinator
 HILL INSPIRATION

Signature of Co-Ordinator
HILL INSPIRATION

Checked & Verified
Shank
 Engineer (Civil)
 HILL INSPIRATION

Signature of Engineer

Name: *SHANKAR*
 HILL INSPIRATION
 Contact no: *8822021848*