



BHADRESWAR MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
S.N.Jute Mill Quater	22.8350135 88.3608269	7	2676.58	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	2	2	2	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	537	11	537	316	Paikpara	

Swapn KR. Das
S.A.E. (B.S.U.P)
BHADRESWAR MUNICIPALITY

Annexure-III (Joint Site Inspection Report)

Visit Date	2026-02-16
Nearest location of CT/PT (approx)	S.N.Jute Mill Quater
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	10
Female Toilet Seats	10
Male Urinal	2
Female Urinal	5
Male Bath	3
Female Bath	3
Children Feed	
Children Feed	
No Of Toilet Seats	
No Of Urinal Seats	
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	Maintained by Mill

Name: Swapan Das

Designation: SAE

Contact No: +91 90074 93077

Date: 24.4.26

Name: Probir Mukhopadhyay

Designation: Civil Engineer

Swapan K.R. Das
Signature with stamp

S.A.E. (B.S.U.P)
BHADRESWAR MUNICIPALITY

Checked & Verified

Probir Mukhopadhyay
Engineer (Civil)

Signature with stamp assigned by Joint Inspection

Site Image

